USING DESCRIPTION

Thank you for buying this product.In order to use this product correctly,you must read this description care fully before using.

1.this product suitable for
2.Must insure the operating environment within allowing range.
3.This product do not including tools

1. Arrange for a FAOC to assemble.

housing
fiber connecting holder
boot cover
screw cap

2. Insert screw cap into optical cable.

3 Fiber length.

2.0/3.0 cable
0.9mm
40mm

2mm*3mm cable
0.25mm
55mm

4. Cut off the fiber at the length of 12mm using optical fiber cleaver.

22mm
12mm

5. Insert optical cable into the fiber guide on the boot .when it is checked the bending of cable as above,stop inserting.

curve the fiber

6. And maintaining the cable bending with right hand,push the connecting holder forward to the end and fix the fiber.

7. Take the boot cover down,connect the screw cap with boot by turning it and make the coating & strength member (yarn)fix.

8. Turn the protrusion of housing toward the bottom and unite it to body.Completion.

0 1cm 2 3 4 5 6 7